


2249Z 23 DEC 64

SECRET

DIRECTOR



ROUTING	
1	4
2	29
3	11
4	12
5	13
6	14
7	15
8	16
9	17
10	18

ROUTINE

TOR: 2325Z 23 DEC 64


OPS 1-10

IN 64384


25X1



INFO



ONE



25X1

SUBJECT: FILM EVALUATION MISSION T314A.

1. CAMERA C-119 WAS USED IN MISSION T314A FLOWN ON 16 DECEMBER 1964. PROCESSING WAS PERFORMED BY

25X1

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD9
 B. 9R SIDE: MINOR ROLLER INDUCED STATIC DISCHARGES ;;49))34 CHATTER) ARE PRESENT INTERMITTENTLY ON THE OUTBOARD (TITLED) EDGE OF THE FILM.

C. 9L SIDE: FRAMES 399-402 CONTAIN SHORT (0.75" LONG) MINUS DENSITY STREAKS SPACED FROM 2" TO 5" APART IN A ROW 1.60" FROM AND PARALLEL TO THE OUTBOARD EDGE OF THE FILM. FRAME 410 CONTAINS NUMEROUS SIMILAR STREAKS. THESE STREAKS DERIVE FROM A SMALL DEPOSIT OF FOREIGN MATTER ON THE FILM.

D. BOTH SIDES: THERE IS NO DATA CHAMBER RECORDED IN FRAME 001. MINOR EDGE STATIC DISCHARGES ARE PRESENT ON THE OUTBOARD EDGE THROUGHOUT THE FILM. THE TITLED FRAMES ARE NUMBERED 0001-2528.

25X1A

Approved For Release 2003/03/04 : CIA-RDP66B00597R000100100074-3

PAGE -2-

S E C R E T

IN 64584

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING
FAULTS.

3. DUPLICATE POSITIVE:

- A. THE PI SUITABILITY IS GOOD.
- B. PRINTING AND PROCESSING ARE GOOD.
- C. THE CLOUD COVER IS 2 PERCENT.

END OF MESSAGE

S E C R E T

Approved For Release 2003/03/04 : CIA-RDP66B00597R000100100074-3